



Purpose:

This document describes the important details for the assembly of FX DC upgrade cables.

1 DC connector specification.



2 DC line current direction diagram.



3 It is recommended that the distance between the single DC connector and the adapter board be within 5cm.

